



Service Bulletin Index

Service Bulletin	Release Date	Part Number	Service Bulletin Description
SB0001 (*)	4/97	None	Shutdown Command
SB0002 (*)	4/97	None	Pinched Control Harness Results in Faults
SB0003 (*)	3/99	None	400 to 480 VAC Wye Connection Required, All MicroTurbines
SB0004	3/99	None	Exhaust Flapper Alignment, C30
SB0005 (*)	3/99	None	Weather Proofing Improvements, C30 prior to S/N 10
SB0006 (*)	3/99	None	Back Pressure Limit Increased to 8 Inches of Water, C30
SB0007 (*)	10/99	None	Fast Under Voltage Setting, C30 software V2.00 and 2.01
SB0008 (*)	12/99	None	Display Menu Changes, C30 after upgrade to V3.05
SB0009 (*)	1/00	None	Fuel Setting – Fuel Index 1 Multiplier, C30 with V3.05
SB0010 (*)	5/00	None	Batt Mgmt Grid Connect or Dual Mode, C30 w/Stand Alone
SB0011	5/99	None	Changes to HEV MicroTurbine Power Supply Grounding
SB0012 (*)	6/00	None	Connecting to Capstone MicroTurbine by Modem
SB0013 (*)	-----	511381-001	BCT - Fan Installation and Control Board Change
SB0014 (*)	-----	511382-001	Rotary Flow Compressor – Bearing Replacement
SB0015	6/01	512100-002	SSR Transient Voltage Suppressor Installation Instructions
SB0016 (*)	10/00	511724-001	Display Panel Problems, C30 Using Liquid Fuels
SB0017 (*)	11/00	511877-001	Scheduled Maintenance on Liquid Fuel Units, C30
SB0018 (*)	7/01	512065-002	C30 Power Connections
SB0019 (*)	-----	-----	Not Yet Assigned
SB0020 (*)	4/01	512275-001	C30 LP Gaseous Fuel System Operational Parameters
SB0021 (*)	7/01	512338-001	Exciter Module Replacement/Ignition Cable Security Inspection
SB0022	7/01	512724-001	SPV Software Update, C30
SB0023 (*)	7/01	512766-001	Stand Alone Battery Pack Service Criteria, C30
SB0024	9/01	512772-001	Dual Mode Controller Relay Update, C30
SB0025	8/01	512771-001	Electrical Input Requirements for C30 and C60
SB0026	9/01	513016-001	Torque Requirements – Electrical Connections, C60
SB0027 (*)	-----	513086-001	Not Yet Released
SB0028	10/01	513113-001	Kerosene Filtration Requirement, C30
SB0029 (*)	10/01	513130-001	V4.56 Stationary Software Upgrade, C30
SB0030 (*)	10/01	513170-001	V4.61 Stationary Software Upgrade, C30
SB0031 (*)	2/02	513547-001	C60 UCB Battery State of Charge
SB0032	2/02	513551-001	Exhaust Damper Valve Required
SB0033	3/02	513571-001	Fuel Gas Booster Electrical Connections, C60
SB0034	2/02	513577-001	TET Thermocouple Replacement, C30
SB0035 (*)	3/02	513645-001	MultiPac Over Current Faults
SB0036 (*)		450000-001	Model C60 Software Release Notes (NOT RELEASED)
SB0037 (*)	5/02	450001-001	Model C30 Software Version 4.76 Release Notes
SB0038	6/02	450002-001	Inspect DMC Terminal Connections
SB0039	10/03	450003-001	Inspect Foil Bearing RFC Heat Exchanger

**Capstone Turbine Corporation • 21211 Nordhoff Street • Chatsworth • CA 91311
Service Bulletin Index**

Service Bulletin	Release Date	Part Number	Service Bulletin Description
SB0040	08/02	450004-001	Battery Breaker Disconnect during Grid Isolation - Model C60
SB0041	08/02	450005-001	External Battery Wake Connections – Model C60
SB0042	10/02	450006-001	Checking Exhaust Dome Alignment – Model C30
SB0043	10/02	450007-001	PowerServer Software Upgrade
SB0044	11/02	450009-001	Replacing Fuel Filter Strainer Cap O-Ring
SB0045 (*)	07/03	450010-001	Unifin-2 Interposing Relay Requirements
SB0046 (*)	12/02	450011-001	Wiring Interlock between Multiple MicroTurbines with Common Exhaust Duct
SB0047	12/02	450012-001	Reconfigure Corner Grounded Delta Configuration
SB0048	12/02	450013-001	3-Way Valve Orientation on Air Assist Circuit
SB0049	01/03	450014-001	HEV Contamination Preventative Measures
SB0050	02/03	450015-001	Pressure Regulator Replacement – C30 Liquid Fuel
SB0051 (*)	02/03	450016-001	Software Version 3.91 Release Notes – C60
SB0052	02/03	450017-001	Software Version 4.93 Release Notes – C30
SB0053	02/03	450018-001	Silencer Improved Sealing – C60
SB0054	04/03	450019-001	HEV Software V2.07 Release Notes – C30
SB0055	04/03	450020-001	Fuel Injector Replacement – C30
SB0056	05/03	450021-001	SPV Version 2.14 Software Compatibility
SB0057	07/03	450022-001	C60 Fan Failures
SB0058	06/03	450023-001	C60 Software Version 3.91 Upgrade Required
SB0059	09/03	450027-001	Backflow Damper Replacement
SB0060	09/03	450028-001	Reserved
SB0061	09/03	450029-001	UCB Input Signal and Ground Isolation
SB0062	01/04	450036-001	C60 ICHP Version 4.10 Software Release Notes
SB0063	01/04	450037-001	CRMS Version 4.34 Software Release for C60 ICHP
SB0064	04/04	450038-001	C60 Version 4.21 Software Release Notes
SB0065	06/04	450042-001	CRMS Version 4.41 Software Release Notes
SB0066	06/04	450043-001	C30 Version 5.01 Software Release Notes
SB0067	06/04	450044-001	C30 HEV Version 2.09 Software Release Notes
SB0068	08/04	450047-001	C30 Generator Terminal Block Nut Replacement
SB0069	09/04	450049-001	C60 Version 4.23 Software Release Notes
SB0070	09/04	450050-001	C60 Version 4.24 Software Release Notes
SB0071	11/04	450051-001	C30 Version 5.03 and Version 5.05 Software Release Notes
SB0072	11/04	450053-001	C60 LIP Water Prevention Retrofit Kit
SB0073	12/04	450054-001	Wiring Interlock b/w Multiple C30 MicroTurbines with a Common Exhaust Duct
SB0074	12/04	450055-001	C60 Version 4.25 Software Release Notes
SB0075	02/05	450056-001	CPS Version 2.11 Software Release Notes
SB0076	06/05	450058-001	C60 Version 4.30 Software Release Notes

(*) Service Bulletins marked with an asterisk have been archived. Contact Capstone Technical Support for details.