



Service Bulletin SB0039

Date: July 2002
From: Capstone Technical Support
Subject: Inspect Foil Bearing RFC Heat Exchanger

Affected

All Low Pressure Foil Bearing RFC Model C30 MicroTurbine systems supplied by Capstone Turbine Corporation®.

Safety Precautions

Only Capstone Authorized Service Providers (ASP's) should open the MicroTurbine and other equipment connected to the MicroTurbine. The systems can include multiple sources of power. Observe and adhere to the Safety Instructions contained within the MicroTurbine manuals.

Summary

Damage may occur to the heat exchanger during shipping or installation. This may result in fuel leaks, which can lead to safety issues or further component damage. Systems should be inspected to ensure that no cracks or visible damage is present at the heat exchanger.

To ensure reliability, an upgrade kit is available for all Low Pressure Foil Bearing RFC Model C30 MicroTurbine Systems and Retrofit Kits, containing an intercooler and bracket assembly.

If you have additional questions, please Capstone Technical Support:

Telephone: (818) 407-3600
Facsimile: (818) 734-1080
Toll Free Telephone: (877) 282-8966
E-mail: service@capstoneturbine.com